Wooden Door Slot Sealing Strip

Door and window sealing strip series

Introduction

Wooden door slot sealing strips are sealing materials designed for wooden doors. They are installed in the sealing grooves of wooden doors to ensure the airtightness and sound insulation between the door and the door frame. They are usually made of materials such as rubber, silicone or polyurethane, and have good elasticity and durability.





Specification

Size

Custom made according to the door frame seal groove size and wood door model, with common sizes ranging from 5mm to 20mm in width, 3mm to 10mm in thickness, and length customizable as needed.

Material

Rubber silicone polyurethane etc.

Surface Treatment

Smooth surface or textured surface to increase sealing effect.

Color

Black gray white or customized according to customer needs.

Functional Features

- · Sealing and waterproofing: The wooden door slot sealing strip can effectively prevent rain, dust and foreign objects from entering the room, keeping the room dry and clean.
- · Sound insulation and shock absorption: The elastic material of the sealing strip can absorb and isolate external noise and vibration, and improve the indoor quiet effect.
- · Environmental protection and durability: Made of environmentally friendly materials, it has good durability and long-term stability, and is not easy to age and deform.




















Strict implementation



Raw Material Inspection Strict inspection, quality standards

Performance Testing

Resistant to low temperature, aging, etc.

Precautions

1. The installation position of the sealing strip should be completely in line with the sealing groove of the door frame to ensure good sealing effect.

Finished Product Inspection

Quality standards

- 2. The sealing groove of the door frame should be cleaned before installation to ensure that the surface is clean and free of oil and dust. Regular cleaning and maintenance can extend the service life of the sealing strip.
- 3. Regularly check whether the sealing strip is aging, deformed or damaged. If there is any problem, replace it in time to ensure the sealing effect.

